

*Official copies of these procedures are maintained at this website.
Before using a printed copy, verify that it is the most current
version by checking the document issue date on this website. Signed
copies of these official procedures are maintained at the Training Office.*

C-A OPERATIONS PROCEDURES MANUAL

ATTACHMENT

8.10.2.b Collider Fence Posting List

C-A-OPM Procedure in which this Attachment is used		
8.10.2		

Hand Processed Changes

<u>HPC No.</u>	<u>Date</u>	<u>Page Nos.</u>	<u>Initials</u>
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

Approved: Signature On File _____
Collider-Accelerator Department Chairman Date

A. Etkin

C-A-OPM 8.10.2.b (Y)

1

Revision 01
September 18, 2000

Collider Fence Posting List

Fence Location	Permanent Postings	Running Period Postings
Perimeter Fence - 1004 – 1008 and Ring Rd. 1005 Area	Caution Controlled Area Area Controlled for Radiation Protection Purposes. For Entry, You Must Have Radiological Training or Be Escorted by a Trained Individual.	
Cryo Pipes		Radiation Barrier, Contact Liaison Engineer Before Removal
Buildings 1002, 1004, 1006, 1008 and 1012 Scrapers Beam Dumps Pads – 1004, 1008, 1012	Caution Controlled Area – See gate for Entry Requirements	At Gate – Contact CAS for Entry
Security Perimeter Fence – 1008 - 1004	At Access Points – Caution Controlled Area	
Pad - 1002	Caution Controlled Area – See gate for Entry Requirements	At Gate – Contact CAS for Entry On Shield Wall – Caution No Climbing No Ladders
Injection Areas on Berm		Caution Radiation Area TLD and RWP Required
Survey Shafts	Radiation Barrier Contact Liaison Engineer Before Entry	